

AS3050

Installation of the conductivity circuit board (LA3050/x)

■ Description

Add or replace a conductivity circuit board to the control type AS3050.

■ General Instructions

- Unscrew the front plate (4 screws)
- Connect the flat cables as shown in the drawing below
- Place the LA3050/1 or LA3050/2 circuit board as shown in the drawing below
- Screw the front plate

■ Pictures



