

OS3050

Installation of the conductivity circuit board (LM3050/x)

■ Description

Add or replace a conductivity circuit board to the control type OS3050.

■ General Instructions

- Unscrew the front plate (4 screws)
- Connect the flat cables as shown in the drawing below
- Place the LM3050/1 or LM3050/2 circuit board as shown in the drawing below
- Screw the front plate

■ Pictures

